UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,882,621 B1

Page 1 of 1

APPLICATION NO.: 09/673533

DATED

: April 19, 2005

INVENTOR(S)

: Jorg Kopp et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page Item 54, and in col. 1, lines 1-3, Title:

Delete [METHOD FOR EQUIVALENTLY CONNECTING SUBASSEMBLIES IN 1:N REDUNDANCY] and Insert -- METHOD FOR STANDBY CIRCUITING OF ASSEMBLIES IN 1:N REDUNDANCY --

Signed and Sealed this

Fifteenth Day of April, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office